

# **WEST VIRGINIA CODE: §22A-2-15**

## **§22A-2-15. Dangerous places.**

The mine foreman shall direct and see that all dangerous places and the entrance or entrances to worked out and abandoned places in all mines are properly dangered off across the openings.