## WEST VIRGINIA CODE: §22A-2-47

§22A-2-47. Responsibility for care and maintenance of face equipment.

Mine operators shall maintain face equipment in safe operating condition. Equipment operators shall exercise reasonable care in the operation of the equipment entrusted to them and shall promptly report defects known to them.