

WEST VIRGINIA CODE: §22a-2-6

§22A-2-6. Requirements for movement of off-track mining equipment in areas of active workings where energized trolley wires or trolley feeder wires are present; premovement requirements; certified and qualified persons.

Mining equipment being transported or trammed underground, other than ordinary sectional movements, shall be transported or trammed by qualified personnel. When equipment is being transported or trammed where trolley wire is energized on the split of air in which said equipment is being transported or trammed, no person shall be permitted to be in by the equipment in the ventilating split that is passing over such equipment, except those directly involved with transporting or trampling the equipment, and shall be under the supervision of a certified foreman. To avoid accidental contact with power lines, face equipment shall be insulated and assemblies removed, if necessary, so as to provide clearance.